CABLOFIL WIRE MESH CABLE TRAY

FAS P SUPPORT

SPLICE LOCATION

FAS P SUPPORT LOCATED AT END OF TRAY.
THE MAXIMUM TRAY OVERHANG SHOULD
NOT EXCEED 2 FEET PER NEMA VE 2.

BP1004